

Application of Structural Fire Design, 29 April 2011,
Prague, Czech Republic




COLOUR CHANGE OF HEATED CONCRETE

RGB colour histogram analysis as a method for fire damage assessment of concrete

Izabela Hager

Cracow University of Technology, Cracow, Poland, ihager@pk.edu.pl




TESTING PROCEDURE



Concrete samples heating






Flatbed scanner for samples scanning and converting to a digital image




RGB colour system

Red, Green, Blue
values from 0 to 255
(R,G,B)
Black (0, 0, 0)
White (255, 255, 255)
Red (255, 0, 0)
Blue (0, 0, 255)
16 777 216 colours





Scion Image v. 4.0.3, (Scion Corporation ©, USA)




TESTING PROCEDURE

Normalized histogram - calibration scale





sandstone, 80x, polarized light microscope

HP concrete, mortar and cement paste




Ordinary concrete, mortar and cement paste



APPLICATION

- non - stationary heating;
- external surface of the concrete specimen $0.30 \times 0.30 \times 0.12$ m;
- R histograms of each slice compared with calibration scale.



calibration scale – external surface of the sample (cube, $a=0,1$ m)



CONCLUSIONS

- Presented method is an practical technique for estimating the maximal exposition temperature of concrete subjected to fire by using an analysis of the colour image;
- a scanner seems to be a useful and simple tool for making digital images of samples/cores resulting in guaranteed consistent lighting conditions;
- colour analysis was performed using the RGB model and the readily available software package Scion Image;
- a calibration scale was produced by taking images of concrete samples heated to temperatures across the 100 - 1000 °C range. The scale can be used to estimate the exposition temperature of concrete in structures subjected to a real fire;
- In practice, several techniques should be combined in order to obtain a complete and accurate picture of the concrete member damage.