


Behaviour of 10.9 Bolts under Fire Conditions

High Temperature Tests



Comparison of the results

